

# 2021 Land Rover Range Rover Velar

P250 S L560 MY21 AWD

**\$54,800**

EGC - Excluding Government Charges



**Enquire Now**

Scan the QR code below  
for more information



|                                                                                                             |                                                                                                                                  |                                                                                                                       |                                                                                                                                    |
|-------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|
|  Year<br><b>2021</b>      |  Body<br><b>SUV</b>                           |  Colour<br><b>Silicon Silver</b>   |  Transmission<br><b>8 SP Sports Automatic</b> |
|  Engine<br><b>2.0 L</b>   |  Kilometres<br><b>46920 Kms</b>               |  Stock #<br><b>P250S2021</b>       |  Power<br><b>184</b>                          |
|  Drive Type<br><b>AWD</b> |  Fuel System<br><b>4 Cyl Direct Injection</b> |  VIN #<br><b>SALYA2AX3MA323975</b> |  Reg #<br><b>EQL59M</b>                       |

THIS 2021 RANGE ROVER VELAR P250 S FINISHED IN SILICON SILVER METALLIC OVER BLACK LEATHER INTERIOR WITH JUST 46,000KMS TRAVELLED FROM NEW.  
THIS RANGE ROVER VELAR FEATURES

  
**Patrick Auto Traders**

**Patrick Auto Traders**  
**Call us on (02) 9000 3867**  
20 22 Carlotta Street, Artarmon, NSW, 2064

Every effort has been made to ensure the accuracy of the information above, however, errors may occur.